

JOHN**McGRATH KIA****AUTO GROUP**

McGrath Canberra Pty Ltd ABN 78 093 024 107
 ACT LMVD 20000228 RTA No.: AU08108 MVRL46403
 PO Box 6215, Mawson, ACT 2607

**KIA MOTORS***The Power to Surprise™*

Cnr Hindmarsh and Melrose Dr, Phillip ACT 2606
 Ph: (02) 6122 2233
 woden.service@jmcg.com.au

Service TAX Invoice				Page 1 of 2				Doc #: KICGW80424			
Customer No. 162975	Customer Name & Address Sellick Consultants Unit 122 24 Lonsdale St Braddon ACT 2612			Advisor GLEN ROBINSON 71383		Colour Clear White/		Team GREEN			
Doc. Date 22/03/22				Year / Make / Model 20/KIA/Picanto 5 Door Hatchback 1.2Lt 4 C		Tag No.					
Reg. No. YOB82D				Model No. G6S6K361B		Carline PICANTO		Eng./Trans. /A			
Stock No. 39142				Chassis No.		Kilometres 19836	Prod. Date 01/12/19	Orig. Del. Date 07/02/20			
Purchase Order No.	Driver	Contract No. 530488		Contract Name CFL		Contract Exp. Kms 200000		Exp. Date 07/02/37			
	Home Phone	Business Phone	Terms Cash	Selling Dealer 82606		Delivery Kms. 10		Delivery Date 07/02/20			
	Vehicle ID. KNAB3512MLT629479		Engine No. G4LAKP113159	Date & Time Promised 22/03/22 04:00pm		Time Received 07:15am		Quote Price			
Mob#: 0424-370083	Sido#: KI629479		Email: Amanda@sellickconsultants.com.au				Warr. Exp. Date 24/02/27		Air Y		
								Pwr Y	Turbo N		

Labour	Operation	Description	Amount
--------	-----------	-------------	--------

Job# 1	01KI62109030C50	Tech(s): 719938 71021	237.24
--------	-----------------	-----------------------	--------

30,000km/24mth service Capped Price Servicing {ModelYr: 2020-2020}

Customer Instructions:

Carried out 30,000km/24 month Kia Capped Price Servicing.
 Replaced Engine Oil with 5W/30 A5
 Replaced Oil Filter with Genuine Filter
 Replaced Sump Plug Washer with Genuine Washer
 Added Genuine Fuel Additive
 Added Genuine Oil System Cleaner
 Replaced Brake Fluid with Genuine Brake fluid
 Replaced Cabin Pollen Filter with Genuine Filter
 Inspected Engine Air Filter
 Inspected Drive Belts
 Inspected Vacuum and Crankcase Ventilation Hoses
 Inspected Exhaust System
 Visually Inspected Battery Condition
 Inspected Brake Lines, Hoses etc
 Inspected Park Brake and adjusted where necessary
 Inspected Disc Brakes and Disc Pad Condition, registered all measurements
 Inspected Power Steering System (For MDPS, inspected Steering Rack etc.)
 Inspected Tyres (pressure & tread)
 Inspected Driveshaft Boots
 Inspected Front & Rear Suspension
 Inspected A/C Compressor
 Inspected Air Conditioner Refrigerant
 Inspected Valve Clearance (Audible Only)
 Fitted Service Reminder Sticker and Reset Service Indicator on Dash Display
 Checked for Outstanding Service Campaigns and Recalls
 Connected Kia Diagnostic System (KDS) and check for DTCs
 Kia Roadside Assistance Activated
 Performed Quality Control Road Test after completing service
 Topped up Windscreen Washer fluid with Genuine windscreen washer fluid
 Carried out Kia Vehicle Inspection Checklist

KI2151323001	GASKET-ENGINE OIL PAN DRAIN	1	2.22
KI2630002503	FILTER ASSY-ENGINE OIL	1	12.24
KI3426889	KIA BRAKE FLUID 500M	1	11.62
KI97133G6000	FILTER ASSY-AIR	1	70.56



KIA MOTORS

The Power to Surprise™

Cnr Hindmarsh and Melrose Dr, Phillip ACT 2606
Ph: (02) 6122 2233
woden.service@jmcg.com.au



Service TAX Invoice					Page 2 of 2		Doc #: KICGW80424							
Customer No. 162975	Customer Name & Address Sellick Consultants Unit 122 24 Lonsdale St Braddon ACT 2612			Advisor GLEN ROBINSON 71383		Colour Clear White/		Team GREEN						
Doc. Date 22/03/22				Year / Make / Model 20/KIA/Picanto 5 Door Hatchback 1.2Lt 4 C			Tag No.							
Reg. No. YOB82D				Model No. G6S6K361B		Carline PICANTO		Eng./Trans. /A						
Stock No. 39142				Chassis No.		Kilometres 19836	Prod. Date 01/12/19	Orig. Del. Date 07/02/20						
Purchase Order No.	Driver		Contract No. 530488		Contract Name CFL		Contract Exp. Kms 200000		Exp. Date 07/02/37					
	Home Phone		Business Phone		Terms Cash		Selling Dealer 82606		Delivery Kms. 10		Delivery Date 07/02/20		Warr. Exp. Date 24/02/27	
	Vehicle ID. KNAB3512MLT629479			Engine No. G4LAKP113159		Date & Time Promised 22/03/22 04:00pm		Time Received 07:15am		Quote Price		Air Y	Pwr Y	Turbo N

Labour	Operation	Description	Amount
	KIAK0C0WS005	WINDSCREEN WASHER SOLUTION 5ML	3.08
	KIC0A39APK00	OIL SYSTEM CLEANER	11.50
	KIKMF300	INJECTOR CLEANER-250ML	9.88
	POL	MAGNATECPRO 5A 5W30	50.75
<<< Total For Job 1 >>>			409.09

Job# 2	03FOZZZZ121	ROTATE AND BALANCE	Tech(s): 719938	27.27
		CARRY OUT WHEEL ROTATION AND BALANCE OF ALL TYRES		
		CARRIED OUT ROTATION OF WHEELS AND BALANCE OF TYRES		
<<< Total For Job 2 >>>				27.27

Job# 3	03FOZZZZ09	WHEEL ALIGNMENT	Tech(s): 719938	45.45
		CARRY OUT FRONT WHEEL ALIGNMENT		
		CARRIED OUT FRONT WHEEL ALIGNMENT AS REQUIRED		
<<< Total For Job 3 >>>				45.45

Misc:RO	1 & 2 CENTS WRITE OFF	0.01
---------	-----------------------	------

Comments

Front tyres 7mm, all okay
Rear tyres 5mm, all okay
Front brakes 8mm, all okay
Rear brakes 8mm, all okay

Total Labour	309.96
Total Parts	121.10
Total POL	50.75
Total Sublet	0.00
Total Misc	0.01
Total Tax	48.18

Total Invoice 530.00

"Please help us to help you....."

Thank you for your continued support of **John McGrath Auto Group**. We trust you are **completely satisfied** with us & would invite you to take a few moments to complete the manufacturer survey when it arrives.

It's your feedback that will help us to maintain the expected high level of service that our customers deserve.

Our goods and services come with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with the service, you are entitled:

- to cancel your service contract with us; and
- to a refund for the unused portion, or to compensation for its reduced value.

You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service.

ST GEORGE EFTPOS
MCGRATH SERVICE
174 MELROSE DVE
PHILLIP 2606
Australia

TIME 22MAR22 17:11
MID 06092274
TSP 1004P3623875
RRN 220322046656
NAB Visa Credit
Visa(C) CR
CARD.....6250
AID A0000000031010
TUR 0000000000
AUTH 452674

PURCHASE AUD530.00

(000) APPROVED

CUSTOMER COPY